Armed Services Technical Information Agency

Because of our lamited supply, you are requested to return this copy WHEN IT HAS SERVED YOUR PURPO. It so that it may be made available to other requesters. Your cooperation will be appreciated.

NOTICE: WHEN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA ARE USED FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED GOVERNMENT PROCUREMENT OPERATION, THE U.S. GOVERNMENT THEREBY INCURS NO RESPONSIBILITY, NOR ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE GOVERNMENT MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE SAIL DRAWINGS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY IMPLICATION OR OTHERWISE AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER PERSON OF CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE, USE OR SELL ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.

Reproduced by DOCUMENT SERVICE CENTER KNOTT BUILDING, DAYTON, 2, 0 HIO

INCI ASSIFIED.

UNCLASSIFIED. Reprit 989

ABSTRACTED

LYCOMING : 💍 .

DIVISION - THE AVIATION CORPORATION WILLIAMSPORT, PENNA.

INITIAL OPERATION OF A SINGLE REED VALVE COMBUSTION CHAMBER

DOWNGRADED UNCLASSIFIED

LYCOMING
DIVISION--THE AVIATION CORPORATION

REPORT NO. 989

Date of Test:

January 28, 1946 to February 9, 1946

ABSTRACTED

Date of Report:

Warch 7, 1946

INITIAL OPERATION OF A SINGLE REED VALVE COMBUSTION CHAMBER

Reported by:

Approved by:

Chief Experimental Engineer

Project Engineer

C. H. Wiegman

Chief Engineer

Distribution:

Mr. C. H. Wiegman

Mr. A. T. Briggs

Engineering Records

Experimental File

Aeropulse Laboratory

Navy Dept. Bureau of Aeronautics (5)

LYCOMING DIVISION-THE AVIATION CORPORATION

REPORT NO. 989

INITIAL OPERATION OF A SINGLE REED VALVE COMBUSTION CHAMBER

Index

· · · · · · · · · · · · · · · · · · ·	
	Page No.
Object	. <u>1</u>
Summary	. ı `
Conclusions	. 1-2
Recommendations	. 2
Description	, 2 -3
Method of Test	3-4
Results or Record of Test	. 4-6
Discussion	6 -8
Record of Test Tabulation	. 9
Figures	. 10
Thermocouple Locations	. 10
Curve	
Curve No. 6619 - Peak Combustion Pressure Vs. Fuel Injections per	
Mim te	. 11
Data and Note Sheets	12-18
Photographs	19-27
Photo No. E-4038 - Valve Parts with Reed on the Seat	19
Photo No. E-4039 - Valve Parts with Reed off the Seat	. 20
Photo No. E-4042 - Assembled Unit with Water Cooling Lines	21
Photo No. E-4041 - Unit with Injection Pumps and Air Tank	. 22
Photo No. E-4040 - Injection Pump with Surge Tank	23
Photo No. E-4036 - Valve with Ram Air Transition Removed	24
Photo No. E-4037 - Downstream View of Valve and Scat	. 25
Photo No. E-4034 - Edge View of Reed No. 3	26
Photo No. E-4035 - Inlet Side View of Reed No. 3	. 27



LYCOMING DIVISION--THE AVIATION CORPORATION

REPORT NO. 989

INITIAL OPERATION OF A SINGLE REED VALVE COMBUSTION CHAMBER

OBJECT:

1. The object of this report is to present the data and observations obtained during the initial operation of a single reed valve on a model combustion chamber for the period thru February 9, 1946.

SUMMARY:

- 2. In order to obtain air flow data on the reed valve proposed for the second combustion chamber to be built under Îtem III of Contract NOa(s)-4718, a single Reed valve was constructed and flow tested. See Reports No. 928 and 936.
- 3. Subsequently this reed valve assembly was welded into a piece of pipe provided with spark plugs and a fuel injection nozzle to form a crude combustion chamber.
- 4. The data given herein cover the results of the preliminary runs with this crude model. Three reed valves were tested under various operating conditions, the maximum time of operation on any one reed was 9 hours and 29.5 minutes. The preliminary results of the tests of this model with the single reed valve were very encouraging and such to indicate that it would be a very useful tool in the development program of a combustion chamber of this type.

CONCLUSIONS:

- 5. It is concluded that:
 - a) A combustion chamber employing a fixed size open nozzle exhaust, an automatic inlet valve and constant spark ignition can be made to fire in cyclic order by injecting fuel at regular intervals.
 - b) The reed valve shows promise as an automatic inlet valve for intermittently firing combustion chambers.

LYCOMING REPORT NO. 989
DIVISION-THE AVIATION CORPORATION

- c) The single reed valve unit is a very useful tool to expedite the development program of a combustion chamber using this type of valve.
- d) The scavenging of the combustion chamber depends upon the location of the exhaust opening as well as the size.

RECOMMENDATIONS:

- 6. It is recommended that:
 - a) A more durable small combustion chamber with water cooling and a better nozzle entrance be constructed for use in endurance testing of single reed valve assemblies.
 - b) A single reed valve combustion chamber should be used for the investigation of temperature drift in dynamic pick-ups.

DESCRIPTION:

- 7. The single reed valve combustion chamber model was assembled as shown on drawing No. 70614 or as illustrated on page 10 of this report. The valve assembly consisted of the valve seat plate on the inlet side, the valve cover or stop plate on the exit side and the valve reed, Lycoming No. 70723 between the two plates.
- 8. Photo No. E-4038 on page 19 shows the reed on the seat with the cover plate at the side.
- 9. Photo No. E-4039 on page 20 shows the reed between the seat plate and cover plate.
- 10. In photo No. E-4042 on page 21 the reed valve assembly is shown attached to the combustion chamber.
- 11. The single reed valve unit was mounted on a test bench and connected to an air supply tank and to a Bosch fuel injection pump as shown on photo No. E-4041 on page 22.

DORES TRACING PAPEL A. RELIGIT CO., PITTEBURG.

LYCOMING DIVISION-THE AVIATION CORPORATION

REPORT NO. 989

- 12. The fuel pump, drive unit, mount and all equipment other than the single reed valve chamber assembly are equipment designed and assembled for other tests and are consequently larger units than would have been required for only the single valve test.
- 13. The fuel pump is made of two units, Bosch numbers EJN7648-62 Serial EG4035-17 and EJN7648-7 Serial EG4035-16.
- 14. The injector nozzle is a Bendix part number 135026 Lycoming serial No. 21.
- 15. The Bosch fuel pump with the surge tank is shown with the drive and electric tachometer in photograph No. E-4040 on page 23.
- 16. The original .281 jet hole is shown in the plate on photo No. E-4041 on page 22.
- 17. Photo No. E-4042 on page 21 shows the fuel injector surrounded by a coil to spray cooling water against the injector end of the chamber. The line for cooling the main chamber is shown above the unit.
- 18. A General Electric Company Catalog 51G2 neon light transformer serial 2004784 supplied a continuous arc through two spark plugs with .050 gap.

 METHOD OF TEST:
- 19. The initial test was conducted on January 28, 1946 with a reed of Brown & Sharpe gage stock as received to find conditions under which the unit would operate. The fuel used during all tests was 73 octane aviation gasoline.
- 20. The first reed was replaced by a reed of the same material heat treated to Rockwell C 40-45 and testing continued on January 29, 1946.
- 21. A surge tank was installed in a line connecting the inlet chambers of the Bosch pumps to minimize the fuel surge.
 - 22. Thermocouples were located as shown on page 10.
- 23. An electric tachometer was connected to the fuel pump drive to determine the I.P.M. (fuel injections per minute).

LYCOMING DIVISION-THE AVIATION CORPORATION

REPORT NO. 989

- 24. The fuel system was connected through a 14 to 220 lb./hr. rotameter and through the Pittsburgh type displacement meter.
- 25. The air tank was connected to pressure gages to record the ram air pressure.
- 26. On February 7, a uniflow ball check valve was installed between the combustion chamber and a 0 600 PSI indicating gage to record peak cylinder pressures.
- 27. With the preliminary instrumentation installed, the plan was to operate in one-half hour intervals starting at 300 IPM and continue with increased IPM until difficulty was encountered.
- 28. In attempts to increase the limiting number of injections per minute, tests were conducted with dual and single ignition, with water spray on the fuel injector end and on the cylinder, and with different nozzle opening combinations.
- 29. Short interval operation was also attempted with auto-ignition.
 RECORD OF TESTS:
- 30. In the summary of test variables shown on page 9, the runs are identified by date and time. The reed valves are identified by number. The letter "R" given after the nozzle diameter signifies a smooth approach.
 - 31. The recorded data are given on page 12 through page 18.
- 32. The first test on January 28, 1946 showed that the unit would operate at around 200 cycles per minute but that the life of the soft valve was of the order of five minutes before mal-firing occurred due to distortion of the valve.
- 33. One hour of operation on January 29, 1946 with the hardened valve indicated continued investigation with preliminary instrumentation was desirable.
- 34. With the hardened valve (#2) the unit would operate at 300 IPM (injections per minute) but mal-firing occurred after short operation at 400 IPM. It was noted that the injector plate temperatures started increasing rapidly with mal-firing occurring within 8 minutes when the IPM was increased from 300 to 400.

D. SOSSE TRACING PAPEL . ELLIOTT CO., PITTEBURGE

LYCOMING
DIVISION--THE AVIATION CORPORATION

REPORT NO. 989

- 35. The second attempt to operate at 400 IPM confirmed the above.
- 36. Number 2 valve was examined and found to be in good condition.
- 37. The valve was installed with the convex side toward the inlet or valve seat side.
- 38. When the top injector end spark plug wire was removed so the unit was operating on the single ignition spark from the jet end plug, the exhaust flame shortened. By increasing the fuel flow the length of the flame was increased and made equivalent to the dual ignition flame. Stabilized operation was possible up to 350 IPM. With this single plug location flash readings indicated that 500 IPM was the maximum value for short interval cyclic operation.
- 39. The top injector end plug wire was reconnected and the jet end plug disconnected. The temperatures of the chamber were higher at 300 IPM than were observed for the 350 IPM operation with the other plug. However, flash operation indicated that smooth cyclic operation with the injector end plug alone was possible up to 800 IPM.
- 40. A water spray was added to cool the fuel injector nozzle end of the chamber, extending stabilized operation on dual ignition from 300 to 600 IPM.
- 41. The maximum cyclic frequency with stabilized operation as in the preceding paragraph was further increased to 1000 IPM by machining a smooth approach in the .281 diameter nozzle.
- 42. A series of flash readings were taken to determine the maximum chamber peak pressures at the various IPM with the optimum throttle setting and with the ram air pressure limited by the output of the 64D9 Ingersoll Rand compressor.

 The results are plotted on Curve No. 6619 on page 11.
- 43. Number 2 reed was daraged in attempting to increase the bow or tension in the reed and number 3 reed was installed.

228 TRACING PAPEL ELLIOYT CO., PIYTSE

REPORT NO. 989

LYCOMING DIVISION--THE AVIATION CORPORATION

- 44. The jet flange gasket ble# out as tests were to be started with a .315 dia. nozzle. The flame first shortened and then increased to the longest flame encountered during the period covered by this report as the fuel supply was increased. Peak combustion pressures were correspondingly increased.
- 45. When normal operation was resumed with the .315 diameter nozzle, the maximum frequency was extended from 1000 to 1200 IPM.
- 46. At 600 IPM the peak combustion pressures were considerably above values recorded for stabilized operation at the same cyclic frequency with other jet openings. After 17 minutes of operation at 600 IPM the cyclic speed was increased to 805 IPM. During this interval, the peak combustion pressure was 200-210 psi with ram air pressures of 50-55 psi. After 4.5 minutes of operation at 805 IPM, the valve failed. The net nozzle area was then increased by drilling three equally spaced .187 inch diameter holes in the nozzle plate close to the outer diameter of the chamber.
- 47. Photo No. E-4036 on page 24 shows the valve reed in place as seen when the ram air approach was removed.
- 48. Photo No. E-4037 on page 25 shows the exit side of the reed and valve seat plate.
- 49. Photos No. 1-4034 and 4035 on pages 26 and 27 show the valve reed as removed from the housing.

DISCUSSION:

- 50. From the first test with the soft reed valve it was apparent that the reed valve had possibilities but that a soft valve was not satisfactory.
- 51. A heat treated valve was operated for one hour. The condition of the valve was found to be quite satisfactory with no indications of deterioration.
- 52. After preliminary instrumentation was installed the valve was tried with the convex side and the concave side toward the seat. Although conclusive tests were not conducted it is believed that the convex side should be toward the inlet

S. GOZZS TRACING PAPE .. ELLIOTT CO., PITTEBURGH

LYCOMING
DIVISION--THE AVIATION CORPORATION

REPORT NO. 989

or valve seat. The best initial bow or tension was not determined.

- 53. The preliminary work with the spark plug locations clearly indicates that the position of the spark relative to the chamber or fuel spray is important. Further work on spark plug locations was deferred for later consideration due to the major differences in the combustion chambers of the single reed valve and the full scale multi reed single cylinder design.
- 54. From the general performance of the unit, it was believed that the major factor which limited the IPM and caused mal-firing during the first few tests was the temperature of the fuel injector nozzle and the gasoline. It was interesting to note that in some cases mal-firing could be overcome by increasing the fuel flow to extremely rich values and then returning to a normal operating fuel flow. Probably the injector was fuel cooled from this procedure. This was not a permanent fix as temperatures would again increase to the point where mal-firing was present. The high fuel temperature of the fuel injector probably caused vapor locks and nozzle dribbling at irregular intervals resulting in mal-firing of the engine. The limiting temperature of the injector end of the cylinder seemed to be of the order of 850°. This value probably would change with the rate of fuel flow. The fuel temperature limitation was apparently overcome by the use of the water spray on the fuel injector nozzle end of the chamber.
- 55. The water line was added to spray water on the top of the chamber to avoid difficulty with portions of the equipment not of primary interest during the tests.
- 56. After the high temperatures around the fuel injector nozzle were reduced by water cooling further increases in the cyclic operating frequency were made by enlarging the effective size of the exhaust jet. The experience with a blown exhaust jet flange gasket and the four hole combination exhaust jet demonstrated that increased performance was dependent upon the location of the exhaust opening as well as the size. With the relatively large ratio between the

. 60225 TRACING FAP! X, KLLIOTT CO., PITTSBURGH

REPORT NO. 989

LYCOMING DIVISION--THE AVIATION CORPORATION

cross sectional area of the combustion chamber and the single nozzle area there were apparently large volumes of unscavenged gas.

- 57. A cylindrical combustion chamber of similar volume but of smaller diameter and with a gradual reduction in cross sectional area to the jet area should improve the scavenging with a single nozzle.
- 58. The failure of the valve occurred at a point where the seat had been erroded by a leak between the reed and the seat. As the leak between the reed and seat increased, the localized heating of the valve probably caused the failure of the read. This condition can be improved by a change in the design or material of the seat.

LYCOMING Division - The Aviation Corporation

¥

FORM 707

ENGINE LOG

Engine Type

Test No.

Sheet No.


AT PREET, PREET,

Compression Ratio.

	KUN NUMBER		_	-	_		_			-	1	-	_		•				_	-		
				10.00	T	Ţ	10	177	L			-			2.5.6	-				-	_	
					T		1	4.40	-			1	十		20.3		4.00	-1:				
	15-				7	190:21	.5	1:20 10.	-		-	3	7		7:38		10.32	-71				
	•	`		N		1				\neg			Q	_	0		N	7		1	7	a
	MY DOL 90741	NO		Š						>	-		Sign	-	ON		20	ar	-7			**
	BOTTOM.					-					-	-							•	1	-	
######################################	30 3015	_	NO			-				-						20	Z	8		-	_	
	S. T ANGIN	┿	+-	t	T	+-	t	+-		 	-	+-:		 '	-	201	28/			-	·	-
	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	4-	1	*	+	4	+	╁	1	1	4-	+	+-	4-	₩			+	\	'	1-	·
		1	T	T		+	\dagger	+	-	E	+	-	-	-	_	1	I	-	-	-	1	
	10x 73		1		1	+	+	-	<u>.</u>	+	+	1	+	+	1	1		1	+	*	1	+
	AUX = 4					1	+	+	1	+	+	+	-	1			Ī	+	+	†	4	1
COM TOP CYL. 249 349 440 245 359 349 340 340 340 340 340 340 340 340 340 340	W- 116								+		-	-		_	ON	ð	NO	+	-	+		
Color Colo	740			•			,	-		-1			-				_	-			<u>4</u>	
			+	1-	-		<u> </u>	+	-	-			-			350	_				3	
	ar was	100	+	1	_		+-	+	_	-	-		+-	-	1	NO	NO				1	
NOTE 1-37-1-4-144			+-	1	-		+-	-	~	-	٠.	-	+	-	***	-	10.65			200		
MOTE STAFFINE MARKET M	-		1	2	T	-	~	L	1		21	4	+	-	20.00	4						
	NOTE		-		y		7			-		Ø	8	0					1	•		
MATE - STATUTE MATE STATE STATE										_				-	_	•		- 		-	-	-
		-																	•	,		-
MATE - STRETME MAY STAR 11/16 21/1 3126 5127 3126 3130 312 3133 313 313 313 313 313 313 313 31							-	-	k.	-	 	-	_	_	_	_					·	-
Colored Colo						1		-	+	+		-	-		-				<u> </u> -	-		-
		I	T			1	+	+	+	+	1	+	+	1	1				1	+	1	1
		-				·	1	+	+	`	+	+	+	-				1		+	1	4
						-		-		-	-	-		_		-			1	-	-	
MATE - STARTING		,					- 1															
		_						-	-		_					· · ·				· ·		
##77##										-												
##7## 166 (169 2:16 2:47 5:26 5:27 5:26 3:39 5:35 3:35 3:37 3:10 3:44 3:45 0:10 3 16	2010	35.55	81.4				<u> </u>	-		_	-	_	2.64	3		2.9.4				`		
		8:51	1:00	2:15	_		_	:28 3				15 3:3	1		_		2.17				-	
STATE PLOE TOP MALEND STATE ST		8	+	0	-		·	0			-	0	_	+	1	4				-	-	1
	C 1711 BY 211 10 1711	-	1	30	100	30	+	+	十	+	+	+	-	+	NO	NO	NO	-	-	-	-	ŀ
VET - MAIN SIZE 2119 2019 2				\$	3	Š	\dagger	十	+	+	+	+	+	+				\dagger	+	-	+	+
Colored Colo	Š							-			-	7.		1				1	+	1	1	+
UET - NAME SIZE 21/18 24/18 24/18 24/18 24/18 24/18 24/18 34/18	SIAF UE	000	É		ð	No		1					<u> </u>	- 4				+	+	-	-	\dashv
MATER STREET	215 WAW 512	21118	201		201R	2018		2 4/8						• • •						-	-	-
MINTER STANT MINTER MINT	2											-		.		187	187		-			
WATER STREET STRE																101	181					
WATER SPIRY: TRUE ON	7													,		187	101				,	
Color Colo	A 1/2///	-		NO	NO	NO							1		NO	No	NO		-			
C C C C C C C C C C		100	Г	NO	No	NO	1.	┼─	-		•	 	├		ON	L	No					-
NOTE SM TO SM ON	()	058	Ţ	3/2	1000	+	1	1-		7	-	 	┿~		 -	_	805					-
MOTE NOTE 6:11 2:10 2:20 3:05 C C C C C C C C C C C C C C C C C C C	W. MU	NO			NO	-	 -	1-	1-	7	+	1-	+-	-	-					-	-	-
NOTE A DENNITES RUNS WHERE TEMPERATURES COULD NOT STABILLIZED BEFORE MALE FIRMS ACCURRED. NOTE B - 18 DENOTES FLASH READINGS WHERE NO ATTEMPT WE STABILLIZE. RUNS WHERE NO ATTEMPT WE	11812.5	11:9			3:05	+	 - -		1	7	-	-	-	-					-			-
MOTE A - "A DENVTES RUNS WHERE TEMPERATURES COULD NOT STABILIZED BEFORE AME FIRMS OCCURRED. ANDE TO STABILIZE. ANDE TO STABILIZE. NOTE C - "C" DENOTES RUNS MADE TO RECURD PEAK CYLINDER!						•		† -	t	\vdash	+-	1		-	-					_	-	
NOTE 6 - 7 DENVITES RUNS WHERE TEMPERATURES COULD NOT STABILIZED BEFORE HAL FIRMG OCCURRED ANDE TO STABILIZE SHOWS WHERE NO ATTEMPT W		-				3)	+	\dagger	+-	-	-	+		-		-		-	<u> </u>	-	-
NOTE A - A DENNTES RUNS WHERE TEMPERATURES COULD NOT STABILIZED DEFONE MAL FIRMG OCCURRED NOTE B - 'S' DENOTES FLASH READINGS WHERE NO ATTEMPT W NOTE C - 'C' DENOTES RUNS WHOE TO RECORD PEAK CYLINDER							1-	+	-	-			+						-	-	-	-
NOTE A - 79 DENNTES RUNS WHERE TEMPERATURES COULD NOT STABILIZED BEFORE MAKE FIRMS ACCURRED. NOTE B - 18 DENNTES FLASH REHOINGS WHERE NO ATTEMPT W. NOTE C - 10 DENNTES RUNS MADE TO RECURD PEAK CYLINDER.							-	+	+	+	-	-	-						-			-
NOTE 8 - 8 DENOTES FLASH READINGS WHERE NO ATTEMPT WE NOTE C - 'C' DENOTES RUNS MADE TO RECURD PEAK CYLINDER I	101	1	130	_1.2		4	Ja JAN	TEM	PERA	TIME	5 60	9	1. 1	38		ļ				-		ļ -
NOTE 8 - 'S DENOTES FLASH READINGS WHERE NO ATTEMPT W. ANDE TO STABILIZE. NOTE C - 'C' DENOTES RUNS MADE TO RECURD PEAK CYLINDER A		╁	110		2	die		CION	1000	0011.	S		•					-	-	-	٠.	ļ.
NOTE C - C DENOTES RUNS MADE TO RECURD PEAK CYLINDER		_1		4.5		• 1	CODI	1000	AT IT	20	977	OF X 3.	-	10	-			-	+ .	-	-	
NOTE C C. DENOTES RUNS MIDE TO RECORD PEAK CYLINDER	3				110	-12	100	3				- 1015		3					,- . .	<u> </u>	+	ļ.,
WORKER - C CENTURE IN VERTURE IN VEHICLE CHINES	The state of the s			700	0//0	1	1.38		CUND	20 0		11111	1	33300	13011	1				1	+	
	1000	J	5		37	Sï	304		ジャル				١			3	-		-	_		,

REPORT NO. 989

THERMOCOUPLE LOCATIONS



"PRECISE"

27 Pages, Regold 12 Test No. Redoct No. 989

Sheet No.

Engine Type

Division - The Aviation Corporation ENGINE, LOG

LYCOMING

FORM 707

GASOK XV

AVIATION

31/15

-7306

73nd

TEST

Compression Ratio.

10:43 Þ Note 1 - The Read Valve as described in Report No. 928 was installed in the test unit and operated for springistics.

The up-tream air pressure was set for 32 PMI gage. The injection pump was timed for approximately 200 injection per minute. The ignition was continuous from the newsformer using two essert place. 050- 250 case case and high tendion lead. The upstream air pressure was taken from the 80 gal. resented of the 10 hp 2 stage dom-10:45 33 1600 -A surge tank was incorporated in the fuel system. A tachometer and thermocouple were incorporated in the set-up.
- During this period of operation, the valve bow was such that the convex side of the walve was toward the 2446 10:20 10:30 10:40 1 Note 8 - The thermocourie was installed thru the injector and of the combustion obsmber near the side opposite the valve. of gate valve. A 30 gal, boiler, soursoted to the Reed Valve Adapter with ar of the valve plate. No distortion was apparent although the valve had been con-560 580 570 590 Note 10- mel-firing again occurred Increasing the fuel flow for a subrt time would reenstate firing. Note 11- The valve was found to be in good condition. Note 5 - The flage shortened. The cylinder started to glow from the jet plate flange to the 2.7 12:06 12:26 12:31 12:34 12:38 :32 303 2:15 0131 K O 303 1210 1600 36 Egraptor in the air system. 1210 303 620 540 35 1210 303 31.7 Note 6 - Mal-firing was accommanded by internatition to anoke. 90:11 100 The valve me found to be in good condition :38 [:43 3/4 Ø 300 1200 1600 300 300 400 344 305 306 mrg pressor and regulated by a dulok activ 640 620 530 540 610 630 22.46 Note 2 - A heat treated valve wes installed. A tacting the stop plate. odmbustion chimber. E) 1.29.46 2.34 3:34 3: 200 N Note 3 1.28.46 200 38 .05 GAL. P.S. I. A. 160 150 * 013 LS TEMP RUN NUMBER 25.32 ¥ 55 8 TIME INTERI NOTE HUSE * 3 = S Ş ş CE . 2 5. 4 B 2 \$ 2

· ...

· 1/2.

Recorded by

W. A

2:39 Z7 Pages, Page 13 Test No. Bebort Me. 989 Sheet No. 2 12.0 300 800 31.2 12.2 81.2 1050 500 3 CONFIDENTIAL 2:10 2:12 1200 1200 | 300 300 0801 4 22 4 0 Operation 3:45 3 E . a by increasing the fuel Compression Rado tene th shore mal-flxing. Engine Type. 540 680 590 655 750 800 auged the f s thought to be responsible for the #/ 550 490 650 . was returned to previous appearance niector and spark plug Note 13 - the air was increased with no change in the fuel setting. Note 14 - The air was decreased with no change in the fuel setting. 3 Division . The Aviation Corporation ENGINE LOG LYCOMING 540 540 with injector end plng only. Note 17 - The mariann Clash operation mak 800 PM Note 18 - The temperative at the fuel nossle w 500 ignition with from the lash THE was about 500 400 570 The Class 550 480 550 FORM 707 4 mortae the nd plag only Note 15 - The maximum 4 Note 16 - Operation 3 OCTANE AVIATION GRSQLINE Mote 12 -2.46 WIN: SEC 18/416 THO UEY END OF 140: ABK. 110: ABK. 1.50 1.8.0 PRESS. VBVR TEMP TER WK. RUN NUMBER R APESS. CERIME. MASER

Recorded by

2.5-46
| 10:05 | 10:15 | 10:25 | 16:35 | 16:35 | 10:45 | 10:45 | 10:45 | 10:57 | 11:07 | 11:07 | 11:07 | 11:22 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 | 11:35 10.00 Z7 Pages, Page 34 Test No. Helicark Ho. 969 830 830 180 Retin Compression Engine Type Date 630 20 Division - The Aviation Cerporation Cibre minutes Tr. Market on ENGINE LOG 450 LYCOMING Note 20 - Unit was fining on suite lenition for was added to sool the 150 330 650 4 mater aprey FORM 707 70 180 300 TANE AVIATION GASOLINE Note 19 - A 4:13.6 (3 AR: ABV 18./14 4 4 4 1.8.1 4 180 F. F. END CHRE 25. MOER MUN NUN AUTE ANNESCR FUEL - 73 OC COME CHILLE F 1 3

Z7 Pagus, Page 15 Yest No. ... Report No. 989 1.25 4:10 4:20 Sheet No. CONFIDENTIAL /50 990 (280 64.5 Engine Type Date 016 improve the hole coefficient. ST. BATT Division - The Aviation Corporation LOG 330 LYCOMING ENGINE Note 21 - The 1et bole approach me curred to reda babba at 2/24 Note 23 - A water coulding surey w ~ 2.00 Note 24 - 4 smooth approach PORM 707 550 870 Note 22 - The KSDO so OCTONE AVIATION GASOLINE MAT SOE 11/107 # . A.K. 700 11 11 11 9.5% CNS X 8. PRESS. TUN NUMBER THE SAME MES TAT

9

27 Pages, Page 16 Report 10. 999 Sheet No. 6 Test No. Date. .. LYCOMING 101 MMC 1

Division - The Avlation Corporation

TEST

ENGINE LOG

Engine Type.

3.28 3.30 3.32 730 600 500 0 1 40 59/ 3:26 3:27 875 800 3 34 CONFIDEN 0 130 urseaure sage to determine Note 27 - the flow meter was Surging more than a normal amount. The surge chamber on the gasoline nump removed and drained. 3.24.5 3:21 Note 28 - The unit was very exition on fuel adjustment to obtain a good flame and regular firing. 2:35 2:45 2:50 2:51 3:00 3:05 3:16 3. 1825 1825 240 244 244 244 312 912 912 1000 1000 1040 1040 60 61.5 61 61.5 61.5 61.5 61.5 2075 2030 2000 2000 1990 2040 23 21 16.9 18 18 21.5 Compression Ratio 1000 950 5.31.62 120 hamber and a 120 56 011 28 5. 9.34.8 5.6 between the combustion 125 130 Note 26 - The unit was stopped to replace the valve plate easier 90 25 125 line 6.34.5 27 2:10 2:15 2:28 2:30 61.7 60.8 0011 0961 0081 9081 0091 Nove 25 - 4 ball check was installed in 150 06 120 sak chamber pressurse. 805 805 51.5 52.5 021 90 1060 1830 1:59 99 911 2.7.46 10.55 11.14 1:55 100 41 600 TANE AVIATION GASOLINE 7.44.5 1.08.5 ij 36 25 2 23.1. 8 8 4 KA: AAKK AAC: AAKK 18/11 1.5.4 * 144. END ** END ET END Sie 533 ¥ - 73 007 FUEL

EVCOMING
Dictaion - The Avention Corporation
ENGINE LOG

ž

YORK JUL


Engine Type Date

CONFINENTIAL Test No.


Z7 Pages, Page 17 Report 50. 989 Sheet No. 6

10.0 Nicholan 10.0	1		いいい						7 7	1	5						7				
### Part Part			1	1										3	mpremic		7			1	
## X E ## X E							_					-		ļ							
18 18 18 18 18 18 18 18		2.7.4	35		-	-	2.8-46		+	-	-	-	_					+	-	+	
	, ,	33	1 3.3.				2:30	N	5	1.8 40.	3.5				3.46	3:53				+	4.20
Color Colo						-	2000	1	2,	300 20.	200		-			2200				8	
CAN		405					1000		3	100 100			_		1100	1100	-			8	
CHANGE PRESS C. S. C.	UR PRESS. P.S.I		_		2					9				_	10	8.00	1		6.5		
	CH'B'R TEMP	r							_	181	-			-		1010		20103	040.20	2	
	KETER LA	*			_	<u></u>		-	-	-	 	-	-		_	18.6		20 8	11 900	19	-
	CANAR! GAL		-	-		-			-		3.		_			4	1_,	1	*	-	+
	TAME ANN'S	S	_		-	-			-		9.36	2				1 15.6		-	-	-	
	TEN40.	S.	-	_	-	-			-	9	7		10	50		86.5	+	2.5	-	-	
17. T. C.	CONES PARESS.			-	_	L		-	-	12,	\vdash	P	1/16	115	1/2	1/2	╂	-			T
												-					-	-			
	MOER TEAM INCOM	4	-								7.0				00	00		00		-	
	VE STAP INV. END	<u>u</u>							-		100				950	240	`	080		-	
FOR THE CONTROL OF TH	VE STOP UET END	او	_		_					-	102				980	096	`	1060			
FARMANCE MANAGEMENT OF STATES AND SECURITY AND STATES A		-		-					**											_	
Minister Minister Market Marke	F INTERNAL	_			*			30:												8/13	*
Mote 32 - The ignition was shut off for one minute to allow sogine to make the state of the solution of the so	74 TUK	-			9.34.				3	8.5										10:45	3
Mote 32 - The read rate and formed to report the state of the forme periods property to the test of increase the boar demonst the read that the state of increase the boar demonst the read that the state of increase the boar demonst the read that the state of increase the boar demonst the read to 1324 demonstration for the state of increase increase of increase the state of increase the state of increase increase of increase of increase of increase increase of increase increase of increase increase of inc		+	1	-	_	**		-	+	+		-	-				1				1
29 - The raid ratio and found to require then 1/6 of the force periods to recent to have the bor. An extension to include the part of the force of t	/c //weeks	+	1	1	1	2	20	8	7	×	1	4	1			33	1	*5	1	+	1
20 - The read range and found to require them 1/6 of the force rescionary requires to rescent the bor. An extension in the box designed the read of the force allows and the late that the box designed the read of the force and the restored from 1 to 20 to 223 demands. 31 - The jet place bold was thoroughed from 200 to 223 demands. 32 - The jet place bold was thoroughed from 120 to over 200 FM; The confirms the made to burther increase the force and the respondent from 120 to over 200 FM; The confirms the made to burther increase the fire angle of the significant was shut off for one minute to allow angles to auto fire. No changes in pressures or lampstructure as were noted. 33 - The ignition was shut off for one minute to allow angles to auto fire. No changes in pressures or lampstructure as were noted.		-	+	1		1		-	1		+	-					+	1	+	+	+
29 — The read value are found to require shouth 1/6 of the fours restorate in the unit of the state to increase the box and the read to the read form the restorate the loss was the read form that was restored from 12 to 2125 demands 23 — The jet plate bold was thorward from 20 to 2125 demands 24 — Engine blew but jet plate general in school one 200 FM; The confirms the need to further footpace the first argument from 20 to over 200 FM; The confirms the need to further footpace the first argument on presence increased from 20 to over 200 FM; The confirms the need to further footpace the first argument on presented from 20 to over 200 FM; The confirms the need to further footpace the first argument on presented of for one minute to allow sarging to substitute and read footpace in presented or further footpace in the fighting was shot off for one minute to allow sarging to substitute and very critical on fund additionally. The confirms was very critical on fund additionally.		-	-	-	-			+	+	-	-	-					1.	-	+-		十
29 - The read value are found to require shout 1/6 of the force perfound; would to reace the bor in eyes. 30 - The let plate hole are fromesed from 201 to 3123 demands. 31 - Degine bleer but let plate sendent in shout one minute. The set lines started to shorten but mes restored by increasing fund from 10 to 31 th. Ar. The set lines started to shorten but mes restored for horself from 10 to 31 th. Ar. The jet lines of the 21 test of the 22 test of the starte. 32 - The jet plate gradet was replaced. 33 - The ignition was shut off for one samute to allog engine to sauto fire. No catange in pressures or tampers was very critical on the additional set from 10 the angine to fire fire one samute to the samuel of the samuel		-		-	-			+	-	-	-	-	-					-		+	+
29 - The red rate are found to require them; 1/6 of the force periodity require to mance the bot. An attended to increase the bot. An attended to increase the bot. An attended to late bot. An attended to late the bot. An attended to late the late blet but let blet blet but let blet blet but let blet blet but let be blet but let blet blet but let blet blet blet blet blet blet blet									-									-	-	-	1
29 - The rest rates and found to require them; 1/6 of the force periods to require to recor the bon, an extension of the jet plate hole mas normaned from 280 to 3125 demote. 30 - The jet plate hole mas normaned from 280 to 3125 demote. 31 - Engine blee, put let blee gament in about one admits. The fact flame started to shorten but mas restored by increasing fuel flow from 16 to 23 th, ave. The monbustion pressure increased from 120 to over 200 EN. The continue the need to brother increase the fet args. 32 - The jet plate gradget was replaced. 33 - The ignition was shut off for one minute to allog angine to suite fire. No changes in pressures or tamper private was vary critical on tust adjustments. The continue was vary critical on tust adjustment. The continue was vary critical on tust adjustment. The continue was vary critical on tust adjustment.									-			-								\vdash	十
29 - The read value was found to require thens 1/6 of the force periods propose to make the bor, An extension in the unit 20 - The jet place hole was more and from 20 to 2125 diameter. 31 - Engine blev put let plate genics in shout one minute. The set flow starred to shorten his was restored by instancing fuel flow from 16 to 31 th the the seasons directly from 16 to 61 th the mass and continues the med to further increase the first single was replaced. 32 - The jet plate genics was replaced. 33 - The ignition was shut off for one minute to allow engine to auto fire. No changes in presenters or temperature and any critical on lues additionally fining and irradials.																	-	-	-	-	-
29 - The rief rate are found to repute them; 1/6 of the force feet only require to recee the bor an extension of the integral to receive the respect to receive the set of the s												-				-					-
30 - The jet plate hole was horsered from 200 to 312% demote. 31 - Engine blev put jet plate gealet in about one minute. The ett flam stirted to shorten but was restored from 120 to 02 10 and The ett flam stirted to shorten but was respected from 120 to 02 20 and The ett flam stirted to shorten but was landered from 120 to 02 20 and The ett flam stirted to shorten but at 120 to 02 20 and The confirms the need to further increase the left plate gradiet was replaced. 32 - The jet plate gradiet was replaced. 33 - The ignition was shut off for one simute to allow snuther to such fire. Mo natures in pressures or tamperstaring was very critical on fuel adjustment. The increase in pressures or tamperstaring was very critical on fuel adjustment.		Kot	8	3		3	Course	2	न्य क्या	4	٠.	Torse	operation	7	quire	3		1		- Tues	
30 - The left plate hole was increased from 200 to 3125 diameter. The increasing fuel flow from 16 to 210 to minute. The set flows started to shorten hit was restored in the confirmation presents increased from 12 to 12 the was structured from 61 to 2 BBT. The nomination presents increased from 120 to ower 200 BBL. This confirms the need to further increase the fet args. 32 - The jet plate gasket was replaced. 33 - The ignition was shut off for one minute to allog engine to auto fire. No changes in presentes or tampers trives were noted. 24 - The fightine was very critical on fuel authintment. Theirs was irranced.		 -	-	to ta		य क्य	. 1	\$	2	1	r three	arlas	4	-3	7 47	tiun a	1				- 7
30 - The left plate hole was moreawed from 200 to 3124 diameter. 21 - Engine blew put left plate easiet in about one minute. The set flow started to shorten but me restone to tocchastion pressure increased from 12 th. br. The new str. sessions dropped from 51 to 43 Fet. The new flow plate gasket was replaced. 32 - The jet plate gasket was replaced. 33 - The ignition was shut off for one minute to allow engine to suto fire. No obtains in pressures or lamperstriam was very critical on fuel adducted. Theirs was frreshier.					1	1	}		-	•	-	-	_		1		+	- +	-	-	, –
21 - Engine bleer but left plate sealet in about one minute. The set flame started to shorten but sea restored from 16 to 21 between dropped from 61 to 42 between dropped from 61 to 42 between acceptantion pressure increased from 120 to over 200 by. The confirms the need to further increase the left plate season was replaced. 32 - The left plate season was replaced. 33 - The ignition was shut off for one minute to allow engine to such fire. No changes in pressures or temperatures was rectioned on fuel adjustment. The increase in the increase of the i		NO	2	- 7	10 S	-	T.	DOLLERE	1		325	diemete	4		1	+	+	+	*	-	+
for increasing fuel flow from 18 to 73 lb by was sign measure dropped from 61 to 43 PBT. The confirms the need to further increase the fet area. The jet plate gasket was replaced. The jet plate gasket was replaced. The ignition was shut off for one minute to allog engine to suto fire. No changes in pressures or temperature was very critical on fuel adjustment. The increasier.		- Kak	33	_	1			1		7		-			, ,				. i		4
nombuskion pressure increased from 120 to over 200 FBI. The confirms the need to further increase that area. 32 - The jet plate gashet was replaced. 33 - The ignition was shut off for one minute to allog engine to auto fire. No change in pressures or temperatures for noted. 34 - The capture was very critical on fuel addustment. Theirs was irresular.		2	*	-						100		+	12 22	1	red	ou .	7		4	1	+
10t area.		-	-						4	٩		3	<u>.</u>	2		4	3	+	7	+	+
32 - The jet plate gasket was replaced. 33 - The ignition was shut off for one minute to allow engine to suito fire. No change in pressures tampers bires was ware noted. 34 - The ingine was very critical on fuel adjustment. Timing was irresular.		<u>.</u>	: 	400	1000	<u>-</u>	.		7	Ģ	3	į	٠.		2	3	4	Increa	the the	-	+
32 - The jest plate gashet was replaced. 33 - The ignition was shut off for one minute to allow engine to suito fire. No obtages in pressures tampers where noted. 34 - The capine was very critical on fuel adjustment. Timing sea irrander.				3			-			1-		-	:		- -			· •) l	
33 - The ignition was shut off for one minute to allog engine to suto fire. No chings in pressures temperatures were noted. 34 - The ingine was very critical on fuel adjustment. Timing see irrander.	•	Note	33	The	at pla		at mas				· -		:	1		!	-	+	-j-	-	- -
33 - The ignition was sput off for one minute to allow engine to suito fire. No changes in pressures temperatures were noted. 34 - The capine was very critical on fuel adjustment. Timing was irregular.			. !			- 1	-						-			;	-	,		} - 	}
tamperstares were noted.		Not	3	,	gnition	10	hut of	tor	7	\$			MILEO				Dr. Co	ì		-	
34 - The engine was very critical on fuel adjustment. Timing ser	,			tamps.	N. SAL		noted.	1	•	,	! 	1 -1					;			- i	
14 - Ind Ingline was very critical on fuel adjustment. Timing sea			,-	,						-		1			1	,	,				
		NO C	3	H	05.10	THA REL		g		The semiar				7		-					


	10.475 10.475	FUEL - 73 OCTANE	WE AVIATION GASOLINE	ON GA.	'SQL. IN	Ŀ.		[ENGINE	50T			Engine Type	ř.		FINE NT	-	Street No.
1947 1948 1948 1949 1940	10475 10475	KUN												3				
				346.	-	-		-	-				-				+	-
Color Colo	Conf. 12 Conf. 13 Conf. 14 Conf. 15			0.53 10	1:01 60		10:14.6						-				-	
CALL OF PRESS S. S. S. C. S. C. C. S. C. S	Chief Chie	× ×		1200 12													÷	
Conference Con	COMP. COLOR TELES. (COLOR COMB. PRESS. P. S. 1. 210 210 200 COLOR COMB. PRESS. P. S. 1. 210 210 200 COLOR COMB. PRESS. P. S. 1. 210 210 200 COLOR COMB. PRESS. P. S. 1. 210 210 200 COLOR COMB. PRESS. P. S. 1. 210 210 200 COLOR COMB. PRESS. P. S. 1. 210 210 200 COLOR COMB. PRESS. P. S. 1. 210 210 200 COLOR COMB. PRESS. P. S. 1. 210 210 200 COLOR COMB. PRESS. PRESS	910	130	•	•		1						+				_	+
		B. CH'B'R TEN		15,	,	0 18.40		-	+		1	-	1	-	1	+	$\frac{1}{1}$	+
COUNTY C	Cont. Cont	TOWNTER	18/118	*	• 1	88	-	-								+		+
THE TOTAL THE COLUMN SEC. 1.0. 2.0. 2.0. 2.0. 2.0. 2.0. 2.0. 2.0	CHANGER WINE 1810 19 20 20 20 20 20 20 20 20 20 20 20 20 20	12 TH	1	14	7	7	-				-					+	+-	_
Children Color Children C		111 78	3	7.5	161			,-										
CT. LINE (N. 1910 77 20 20 20 20 20 20 20 20 20 20 20 20 20	### CAMB PRESS P.S. 210 205 205 CT. MACH. T. 106 15 10 200 W. W. STOC. W. T. 100 15 10 10 10 10 10 10	S TEMP		3	8.2 59							-						-
C. N. LINE (R. 7700 IN. E.) 6.50 W. M. S. 7700 IN. E.) 6.	C. T. LINE OF THE COLUMN END 7- 90 WELL W. STOP INL. END 7- 6550 WELL W. STOP INL. END 7- 6550 WELL W. STOP INL. END 7- 6550 WATER WANTER AND WAS 700 (Absente 1st pale per state). Birth 13-71 is a part of the column of the	3	Sign	2	10 216	_												
W. W. STOCK THE WALL WAS 100 121 100 100 100 100 100 100 100 100	W. W. STAD W. E. W. F.	110000	- 1 -	-							•	-						
WOTE WINNERS 35 500 1210 1210 1210 1210 1210 1210 1210	WOLE MANAGER	THE CALL THE	. [-	36		 											1
### 1725144	### ### ### ### ### ### ### ### ### ##	15 5 10 mm		+	000			-	+			+	+		-	1	-	1
WOTE AUMERY 35 36 36 36 36 36 36 36 36 36 36 36 36 36	7076 7006 100 100 100 100 100 100 100 100 100	71	1	+	2	1	1	-	+		+	-	+		+	<u> </u>	1	+
WOTE ANAMESP 36 36 WEED 15 - Tree 3/16 dimeter let bake was clear, wil-fring gammed as from the an approximation of the first section we stopped than mal-first occurred the fallure.	NOTE NUMBER 35 - Pare 2/16 clauser 1st tolds were stant. Interior 1st tolds were stant.	4	707. M	-	-	-	3/6.	-										1
WOTE NUMBERY Bade 35 - Three 3/16 disaster, let inches serve shad. Bal-firing nonured at 1000 FM on operating the service and a shopped stan and firing control the territy of the service and a shopped stan and firing.	WOTE NUMBER Both 35 - Enve 3/16 diameter jut holes pure a sheet, bell-futing potentrial at 1000 TPM to operate max ambused to 600 TPM to operate max at the sextine max at the s	3	*****	0.4.6	-		10:11				1		-		1			
MOTE MANGERY Bade 35 - Tree 5/16 clauster, 1st boles was shad, ind-chring noursed at 1000 378 to operate the saids was stopped and sall-first coursed the territories.	WOTE NUMBER 36 36 36 36 36 36 36 36 36 36 36 36 36						-		-				-	-				-
Marke 31 - Three 3/16 dearter let note processed at 1000 174 to operate the ordinary of the or	Bets 35 - Tyres 3.76 Glamater Jet poles pers stand, 1911-firing parameter of a non-year of persons and the society of a stopped stan self-firity cockerred the faithful persons and the society of the so	NOTE NUMBER		36			36											-
Bote 35 - Three 2/16 diameter ist toles were sided Bell-firing politicing of the columns of the	Men 31 - Three 3/16 disserter list holes pure stand. Ball-firling nonurred at 1000 IN to inperse a stand and the first of					-			+				-		-			-
Mark 35 - Three 3/16 diameter jut solve pure aided, Mail-during octouried at 1000 JPL to operate the engine me a roomet men and-during octouried at 1000 JPL to operate the engine me a roomet men and-during octouried the to wait failure.	Beta 35 - Three 3/16 classics, 1st holes sees sized. Bel-firing admired at 1000 JPL to logaria. Bata 26 - The ending we stoom selection as 1-firing options of the Edward fallung.					-					-		-				-	_
Hote 35 - three 5/16 dearter july tolds were stand, bull-fixing occurred at 1000 TP4 to party. Hete 36 - the excise was stopped then sell-fixing occurred the trailer.	Bete 35 - Three 3/16 diameter 1st tolon was added, Bal-firing noturned at 1000 FP to lower the same and the s											-	-					-
Motor 26 - The engine was attorned that an anal-Circle cocurred the to valve failure	Mote 34 - Three 3/16 disacter let toles properties at 1000 174 to topara			-	1	1												
	Mark We are a thoron and a thor			36	1	7 7 0		1		_		•				 -		
Mark 16 - The engine we stooded went and -first or ordinary	Mare No environment and the formal management of the formal management				1	The Carl	wy 9	100			1110	9	2	1	8	+	+	-
The working was also wood with and -firelist occourred the to well-	Move the engine we stopped with sail-firthy occurred the to velve			<u> </u>	_				:	-				1			-	1
				Nete N			3				13	<u> </u>						-
						_										_		
				_		•					- +					-	-	
						_			;									
		1			-	- +	-						;	-				
				_	-	-				_			***************************************					
		!					!	». !			. !		- 1					
		-		;			, , 	: : 			! ! !	_			-		-	-
			·——·		<u>.</u> !			: ! !-			!	r nakan	<u>.</u> 		-	· · · · · · · · · · · · · · · · · · ·	-	-
				1	:				-	•								+
									•	•	•						!	
				,													-	
					ŀ										ı			
												,		,				
									-									;

























27 Pages, Page 26 Report No. 989 Photo No. E-4034



27 Pages, Page ?7 Report No. 989 Photo No. E-4035

